



National Maritime Safety Authority
Papua New Guinea

Notice to Mariners

03/17 (T)

Kila Rear Light is UNLIT

Locality: Vabukori
The light beacon, Oc 6s 90m 10M (9° 29.790'S, 147° 11.330'E)

Chart affected: Aus 505 and Aus 621

04/17 (T)

Cape Ward Hunt Light is UNLIT

Locality: Douglas Harbour
The light beacon, Fl 4s 65m 10M (8° 03.686'S, 148° 07.680'E)

Chart affected: Aus 521 and Aus 522

05/17 (T)

Buluma East Light is UNLIT

Locality: Stettin Bay
The light beacon, Fl R 3s 6m 4M (5° 31.315'S, 150° 18.067'E)

Chart affected: Aus 396, Aus 547 and Aus 674

06/17

R2B Change in light position

Locality: Caution Bay
The light buoy, Fl R 3s 6M (9° 17.900'S, 146° 55.560'E)

Chart affected: Aus 647

Authorised by: Maritime Operations

Issued: 23 March 2017