



National Maritime Safety Authority
Papua New Guinea

Notice to Mariners

16/17 (T)

Metocean Survey
Fugro Survey Pty Ltd

Locality: Coral Sea

In reference to NTM 14/17 (T) mariners are advised of change to positions of recently deployed buoys, Surface buoy 10° 47.56'S, 149° 13.05'E and Sub-surface mooring buoy 10° 48.12'S, 149° 13.9'E.

An exclusion zone of 0.5M radius exist around each buoy.

Authorised by: *Maritime Operations*

Issued: *14 December 2017*